Scope of Work for Property Located at:						8607 North Servite Drive, Unit #112					
	Property is:	Single Fam	ily 🗆	Duplex		Other⊡	Condominium				
Date:	10/27/2015		_								
Below is the <u>minimum requirement</u> to meet health and safety issues. The City of Milwaukee, the Redevelopment Authority, and their representatives take no responsibility for problems discovered after the inspection date, or for omissions through error or oversight. The list does not necessarily include work required by private lenders, insurance companies, or by the Federal Block Grant or HOME programs.											
Exterior Condition Report											
Location Site	Required Worl	(	n/a □	Yes □	Note/ Self H	Comments		\$	Cost		
	Steps/Handrails		n/a □	Yes □				\$			
	Service walks		n/a 🗖	Yes □				\$			
	Fencing		n/a □	Yes □				\$			
	Parking		n/a 🗖	Yes □				\$			
	Retaining walls		n/a □	Yes □				\$			
	Other		n/a □	Yes □				\$			
	Other		n/a 🗖	Yes □				\$			
Garage	Singles: repair		n/a 🗖	Yes □				\$			
	Shingles: Roof over	existing	n/a □	Yes 🗖				\$			
	Shingles:Tear off &	re-roof	n/a 🗖	Yes □				\$			
	Gutters/downspout	S	n/a 🗖	Yes □				\$			
	Flashing		n/a □	Yes □				\$			
	Eaves		n/a □	Yes □				\$			
	Siding		n/a □	Yes □				\$			
	Doors		n/a □	Yes □				\$			
	Windows		n/a 🗖	Yes □				\$			
	Slab		n/a 🗖	Yes □				\$			
	Paint		n/a 🗖	Yes □				\$			
	Electrical		n/a 🗖	Yes □				\$			
	Other		n/a 🗖	Yes □				\$			
Porches	Roof		n/a □	Yes	_			\$			
	Deck-upper		n/a □	Yes 🗖				\$			
	Decklower		n/a □	Yes □				\$			
	Steps/handrails		n/a □	Yes 🗖	_			\$			
	Ceiling		n/a 🗖	Yes 🗖				\$			
	Guardrails		n/a □	Yes				\$			
	Structural		n/a □	Yes □				\$			
	Paint		n/a □	Yes				\$			

\$

n/a Yes 🗆

Other

## House

Chimney	n/a □	Yes □	\$
Shingles: repair	n/a 🗖	Yes □	\$
Shingles: Roof over existing	n/a □	Yes □	\$
Shingles:Tear off & re-roof	n/a □	Yes □	\$
Gutters/downspouts	n/a □	Yes □	
Flashing	n/a □	Yes 🗖	\$
Eaves	n/a □	Yes □	\$
Siding	n/a □	Yes 🗖	\$
Storm Doors	n/a <u></u> □	Yes 🗹	\$ 300.00
Prime ("main") Doors	n/a □	Yes 🗖	\$
Storm Windows	n/a 🗖	Yes □	\$
Prime ("main") Windows	n/a □	Yes 🗖	\$
Paint	n/a □	Yes □	\$
Foundation	n/a □	Yes □	\$
Electrical	n/a 🗖	Yes □	\$
Other	n/a □	Yes □	\$
Other	n/a □	Yes □	* \$
Other	n/a 🗖	Yes 🗖	\$
Other	n/a 🗖	Yes 🗖	\$

Exterior: Estimated Cost:\* \$ 300.00
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Mechanical	Unit: Entire unit (single family) Upper unit of duplex Required Work	<b>2</b>				Lower unit of duplex Other	_ _	
Heating	Repair/replace boiler	n/a	<b>J</b>	Yes		_		\$
	Repair radiation	n/a	IJ	Yes				\$
	Repair/replace furnace	n/a	IJ	Yes				\$
	Repair ductwork	n/a	J	Yes				\$
	Replace thermostat	n/a	Ø	Yes				\$
	Repair/replace grilles	n/a	Į.	Yes				\$
Floatical	Tune boiler/furn. insp ht exchange	en/a	IJ.	Yes		_		\$
Electrical	Repair/replace receptacles	n/a	Ø	Yes		_		\$
	Repair/replace switches	n/a	J	Yes		_		\$
	Repair/replace fixtures	n/a	Ø	Yes				\$
	Install outlets and circuits	n/a	J	Yes		_		\$
	Install outlets and circuits	n/a	J	Yes		-		\$
	Install outlets and circuits	n/a	<b>J</b>	Yes		_		\$
	Install outlets and circuits	n/a	Ø	Yes				\$
	Upgrade service	n/a	Ø	Yes		_		\$
	Other	n/a		Yes				\$
	Other	n/a		Yes				\$
Plumbing	Repair/replace kitchen sink	n/a	<b>J</b>	Yes		_		\$
	Repair/replace kitchen sink fauce	t n/a	IJ.	Yes				\$
	Repair/replace tub	n/a	<b>J</b>	Yes				\$
	Repair/replace tub faucet	n/a	Ø	Yes		_		\$
	Repair/replace toilet	n/a		Yes	<b>J</b>	_		\$ 300.00
	Repair/replace lavatory	n/a	Ø	Yes		_		\$
	Repair/replace lavatory faucet	n/a	Ø	Yes		_		\$
	Repair/replace wash tub	n/a	Ø	Yes				\$
	Repair/replace wash tub faucet	n/a	Ø	Yes				\$
	Unclog piping:	n/a	Ø	Yes		_		\$
	Repair drain/waste/vent piping	n/a	Ø	Yes		_		\$
	Repair water piping	n/a	J	Yes				\$
	Repair/replace water heater	n/a	J	Yes		=		\$
	Other	n/a		Yes	<b>J</b>	Dryer Vent		\$ 150.00
	Other	n/a		Yes				\$

Windows								
	Replace broken glass	n/a	<b>J</b>	Yes			\$	
Deere	Repair or replace sash	n/a	<b>J</b>	Yes		_	\$	
Doors	Repair or replace doors	n/a	Ø	Yes			\$	
	Repair or repl. locks/latches	n/a	v	Yes		Self Help	\$	
Walls/Ceiling	Repair or repl. @ defective	n/a		Yes	Ø	-	\$	850.00
Paint	Repair or repl. @ defective	n/a	Ø	Yes	_		\$	
Fire Safety								
	Install smoke/CO alarm:bsmt.	n/a	Ø	Yes		Self Help	\$	
	Install smoke/CO alarm: 1st flr.	n/a	<b>J</b>	Yes		Self Help	\$	
	Install smoke/CO alarm: 2nd flr.	n/a	J	Yes		Self Help	\$	
Handrails	Repair/replace defective	n/a	Ø	Yes		Self Help	\$	
Stairs	Repair defective	n/a	Ø	Yes	п		\$	
Floors	Repair defective	n/a		Yes			\$	
Other	riepair delective	II/a	<u> </u>	103	<u> </u>	_	Ψ	
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
						Interior: Estimated Cost:	\$	1,300.00
						Total Exterior and Interior Cost:*	\$	1,600.00

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

Inspected by: Jeremy Belot Date: 10/28/2015

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 West Mill Road.